

**APPENDIX C**

**PHOTOGRAPHS FROM SEPTEMBER 2006 SITE INSPECTION**

Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona




Photograph 1  
Transformer and electrical panels adjoining the south side of evaporation pond.



Photograph 2  
West side of the evaporation pond.



Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 3  
View showing the fence around the pond and remaining storm water accumulation within the pond.



Photograph 4  
East end of the evaporation pond.

Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona




Photograph 5  
PLS aboveground tank located in the tank farm adjoining the evaporation pond to the west.



Photograph 6  
Another view of the PLS tank showing the north side of the tank.



Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 7  
Non-potable water tank in center view, sodium hydroxide tank to the left. Tanks were reportedly empty and not in use.




Photograph 8  
Sodium hydroxide tank in the tank farm area.

Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 9  
View of the piping in the tank farm and sulfuric acid storage tank.



Photograph 10  
View showing the sulfuric acid tank and small air compressor in the tank farm.



Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 11  
View showing the raffinate tanks.



Photograph 12  
View of the ground around the raffinate tanks.

Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 13  
View of the piping around the raffinate tanks.



Photograph 14  
View showing the piping and other equipment in the tank farm area with the evaporation pond in the background.



Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 15  
View along the east side of the tank farm. The evaporation pond is to the left in the photograph.



Photograph 16  
View looking east across the evaporation pond.

Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 17  
Closer view of the evaporation pond; storm water accumulation within the pond.



Photograph 18  
Photograph of the pipelines leading from the tank farm toward the well field.



Site Investigation Plan  
Florence Copper In-Situ Mine Project  
Florence, Arizona



Photograph 19  
View showing the origination point of the pipeline going to the well field.